



SNÄCKVÄXLAR

WORM GEAR UNITS

Effekttabell

NRV (n1 = 1400)

Performance

M2 Nm	i	P1 kW	n2 1/min		Fr1 N	Fr2 N	
290	7.5	6.3	186.7	NRV 090	900	3081	67
310	10	5.1	140.0		1082	3391	
360	15	4.1	93.3		1257	3882	
355	20	3.1	70.0		1270	4273	
340	25	2.4	56.0		1270	4603	
410	30	2.6	46.7		1270	4891	
360	40	1.8	35.0		1270	5383	
340	50	1.4	28.0		1270	5799	
320	60	1.1	23.3		1270	6163	
285	80	0.83	17.5		1270	6783	
270	100	0.67	14.0		1270	7306	
480	7.5	10.4	186.7		NRV 110	1200	
520	10	8.6	140.0	1463		4285	
570	15	6.5	93.3	1603		4905	
560	20	4.8	70.0	1700		5399	
590	25	4.1	56.0	1700		5816	
630	30	3.9	46.7	1700		6181	
610	40	2.9	35.0	1700		6803	
600	50	2.3	28.0	1700		7328	
560	60	1.9	23.3	1700		7787	
490	80	1.3	17.5	1700		8571	
460	100	1.1	14.0	1700		9232	
750	7.5	16.1	186.7	NRV 130		1500	5092
820	10	13.5	140.0		1845	5605	
920	15	10.3	93.3		2070	6416	
910	20	7.8	70.0		2100	7062	
930	25	6.5	56.0		2100	7607	
1040	30	6.4	46.7		2100	8084	
1050	40	4.9	35.0		2100	8897	
980	50	3.8	28.0		2100	9584	
900	60	3.1	23.3		2100	10185	
840	80	2.3	17.5		2100	11210	
740	100	1.7	14.0		2100	12076	
1200	7.5	25.8	186.7		NRV 150	1950	6962
1240	10	20.2	140.0	2267		7663	
1250	15	13.9	93.3	2285		8771	
1300	20	11.1	70.0	2674		9654	
1200	25	8.4	56.0	2800		10400	
1200	30	7.1	46.7	2800		11051	
1550	40	7.3	35.0	2800		12163	
1400	50	5.4	28.0	2800		13103	
1260	60	4.2	23.3	2800		13924	
1150	80	3.1	17.5	2800		15325	
1000	100	2.3	14.0	2800		16508	